















Parts List

| | | |
|--|---|---|
|  |  |  |
| Top x1 | Base x1 | Bung x1 |
|  |  |  |
| Gasket x1 | No.6 x 19mm Screw x4 | Black M4 x 14mm Bolt x4 |

Tools Required

| | |
|---|---|
|  |  |
| Pozi Screwdriver | Silicone |
|  |  |
| ø2.5mm (3/32") ø3mm (1/8") Drill Bit | Required Cable Hole Drill Sizes Max. ø15mm (19/32") |



UK & International +44 (0)1392531280 sales@scanstrut.com
 For further installation and warranty information please visit: www.scanstrut.com
 USA +1 860 308 1416 usasales@scanstrut.com